

Facilities Services Inspections

Fire Extinguisher			
Inspection Cost	Contact Name	Contact Office	Notes
\$20.00/ month	Kim Harmon, 974-5084 for billing; Suzanne Rimmer conducts inspections	Environmental Health and Safety	To install or replace a #5 ABC extinguisher \$47.97 each; to recharge or refill #5 ABC is \$19.75

Elevator			
Estimated Cost	Contact Name	Contact Office	Notes
varies: \$272.12, \$827.19 or \$849.03	Terry Ledford, tledfor1@utk.edu	Facilities Services	Completed by UT Vendor monthly. Or, you can choose own vendor with Terry's approval

Health & Safety			
Estimated Cost	Contact Name	Contact Office	Notes
no cost for inspection	Suzanne Rimmer, smc@utk.edu	Environmental Health and Safety	

Fire Sprinkler			
Estimated Cost	Contact Name	Contact Office	Notes
\$150 or \$250	Brad Johnson at Morristown - 865-689-4480	Office of Sorority & Fraternity Life	Completed by Morristown Sprinkler every 6 months; Tenea Lowery is UTK contact

Fire Suppression System			
Estimated Cost	Contact Name	Contact Office	Notes
varies \$75 - \$300	Jack Belcher at Rapid Fire 865-453-0189	Office of Sorority & Fraternity Life	Completed by Rapid Fire every 6 months.

Fire Panel Monitoring System			
Estimated Cost	Contact Name	Contact Office	Notes
varies \$1,292 - \$2,500	Electric Shop at Facilities Services	Simplex or BST/Facilities Services	Completed by Simplex or BST annually; typically over summer months.

Domestic & Irrigation Backflow			
Estimated Cost	Contact Name	Contact Office	Notes
approx. \$200	Robby Huggins in the Plumbing Shop at Facilities Services	Facilities Services	This inspection is required by KUB

Boiler Inspection			
Estimated Cost	Contact Name	Contact Office	Notes
If house has a boiler \$75 - \$227.25		Facilities Services	

*If a member of Facilities Services attends the inspection with an outside representative the hourly rate for that staff member will also be billed.